



## 909D/909D-A PGM Hat Tree Rack

### Assembling Guide

- |                 |         |
|-----------------|---------|
| (1) BASE        | 1 pc.   |
| (2) SPRING      | 1 pc.   |
| (3) INNER POLE  | 1 pc.   |
| (4) OUTER POLE  | 1 pc.   |
| (5) HAT HOLDER  | 20 pcs. |
| (6) HOLDER BASE | 5 pcs   |
| (7) TOPPER      | 1 pc.   |



(1)



(2)



(3)



(4)



(5)




(6)



(7)


**PGM<sub>Plus</sub>**



**Step 2**  
Gently place **SPRING** on top  
of the **BASE**.

**Step 1**  
Place **BASE** firmly on the ground.

**Step 3**  
Insert **INNER POLE** into the  
**BASE** through **SPRING**.



*Make sure to twist the screw tightly after  
**INNER POLE** is inserted into the **BASE**  
completely.*

*Make sure to have **INNER POLE** standing on the end of the foot pedal.*



**Step 4**

**Slide OUTER POLE over INNER POLE.**



*The top of INNER POLE must be aligned like this while stepping down the foot pedal.*

*When sliding OUTER POLE, make sure you are stepping down on the foot pedal with the top of INNER POLE aligned.*

**Step 5**


**Slide HOLDER BASE over OUTER POLE and twist the screw tightly. You may adjust the height based upon your need.**





**Step 6**

**Insert HAT HOLDER into SCREW RING respectively.**



*Insert 5 sets like this*



**Congratulations !! Installation Complete**